

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/13/2018

Submitted Date:

06/28/2018

Document Number:

688800164**FIELD INSPECTION FORM**
 Loc ID 316806 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 56680Name of Operator: MERRION OIL & GAS CORPAddress: 610 REILLY AVENUECity: FARMINGTON State: NM Zip: 87401**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:11 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Joyner, Ryan		rjoyner@blm.gov	
Fischer, Alex		alex.fischer@state.co.us	
Thompson, Philana	(505) 324-5300	pthompson@merrion.bz	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
107769	PIT	AC	09/23/1999		-	HAMM CANYON FEDERAL	AC
232844	WELL	PR	06/05/1980	GW	113-06033	HAMM CANYON-FEDERAL 14-26 1	EI

General Comment:

On June 13, 2018 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Merrion Oil and Gas Corp. Hamm Canyon Federal 14-26 #1, in coordination with the BLM. For the most recent field inspection report for this facility, please refer to document #680401071.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:	Tanks are labeled with contents and capacity, and have NFPA labels.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Open topped tank does not have labels or placards.		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	07/27/2018
Type	WELLHEAD		
Comment:	Free standing sign near well head.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Posted on location sign.

Corrective Action: _____ Date: _____

Good Housekeeping:			
Type	WEEDS		
Comment:	Weeds present near fired equipment.		
Corrective Action:		Date:	

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Perimeter fencing around well head.		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Perimeter fencing around horizontal heated separator.		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Perimeter fencing around tank battery.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Dehydrator	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<50 BBLS	Open Top		38.120071,-108.833046	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				
				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	1	400 BBLS	STEEL AST		38.120169,-108.833361	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:				Date:		
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	100 BBLs	STEEL AST		38.120214,-108.833348	
Comment:						
Corrective Action:				Date:		
<u>Paint</u>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:				Date:		
<u>Venting:</u>						
Yes/No						
Comment:						
Corrective Action:					Date:	
<u>Flaring:</u>						
Type						
Comment:						
Corrective Action:					Date:	

Inspected Facilities									
Facility ID:	<u>107769</u>	Type:	<u>PIT</u>	API Number: <u>-</u>	Status:	<u>AC</u>	Insp. Status:	<u>AC</u>	
Facility ID:	<u>232844</u>	Type:	<u>WELL</u>	API Number:	<u>113-06033</u>	Status:	<u>PR</u>	Insp. Status:	<u>EI</u>

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PITType: BlowdownLined: NOPit ID: 107769Lat: 38.120412Long: -108.833075

Reference Point: _____

Other: _____

Length: _____

Width: _____

Lining:

Liner Type:

Liner Condition:

Comment:

Operator shall submit a Form 27 to close this historic pit in the COGIS database.

Corrective Action

Date: c**Fencing:**

Fencing Type:

Fencing Condition:

Comment:

Corrective Action

Date:

Netting:

Netting Type:

Netting Condition:

Comment:

Corrective Action

Date:

Anchor Trench Present:

Oil Accumulation:

2+ feet Freeboard:

Comment:

Corrective Action

Date:

COGCC Comments

Comment	User	Date
<p>On June 13, 2018 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Merrion Oil and Gas Corp. Hamm Canyon Federal 14-26 #1, in coordination with the BLM. For the most recent field inspection report for this facility, please refer to document #680401071.</p> <p>During this inspection it was noted that the earthen berm around the open topped produced water vessel may need to be repaired to provide adequate capacity. The open topped tank does not have labels or an NFPA placard.</p> <p>Pit Facility ID #107769 is a historic pit with an active status in the COGIS database. The operator is coordinating with the BLM regarding this pit closure. A Form 27, required by Rule 905.b, shall be submitted by the operator to close this pit in the COGIS database.</p>	hughesj	06/27/2018

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
401688641	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4509013
688800165	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4509012