

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/27/2018

Submitted Date:

06/28/2018

Document Number:

679700984

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: ALLISON, RICK On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10071
Name of Operator: HIGHPOINT OPERATING CORPORATION
Address: 1099 18TH ST STE 2300
City: DENVER State: CO Zip: 80202

Findings:

- 2 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Singer, Sheila		ssinger@hpres.com	
Barber, Matt		mbarber@hpres.com	
Axelson, John		john.axelson@state.co.us	
Jeremy Ferrin		dnr_cogccenforcement@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
448950	LAND APPLICATION SITE				-	SANDY HILL 5-61-29	EI
452946	SPILL OR RELEASE	AC	11/07/2017		-	Sandy Hills Spreadfield	EI
454016	SPILL OR RELEASE	AC	02/09/2018		-	Sandy Hill 5-61-29	EI
455617	SPILL OR RELEASE	AC			-	Sandy Hill 5-61-29	EI
455618	SPILL OR RELEASE	AC			-	Sandy Hill 5-61-29	EI

General Comment:

Inspected Facilities

Facility ID: 448950 Type: LAND API Number: - Status: Insp. Status: EI

Facility ID: 452946 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

Facility ID: 454016 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

Facility ID: 455617 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

Facility ID: 455618 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

Environmental

Waste Management:

Type	Management	Condition	GPS (Lat)	(Long)
Drill Cuttings	Land Application	Adequate		
Comment	Cuttings and drilling fluid have been incorporated. Standing water from storm remains on land application site.			
Corrective Action				Date:

Spill/Remediation:

Comment:	COGCC Inspection, response to two spills reported by Operator. Spills occurred during 3-5" rain and subsequent runoff. Stormwater control berms failed to contain runoff and dilute drilling fluid mixed with rainwater impacted State Land Board property to west and private property to south. Berms and ditch have since been repaired. Evidence of drilling fluid and mud is present on offsite properties. No standing liquid was observed on offsite property.		
Corrective Action:	Consult with both landowners regarding cleanup and ensure compliance with COGCC Table 910-1. Incorporate remediation plans into existing Remediation Project 11244 and report remediation progress using eForm 27.	Date:	07/31/2018

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401690250	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4510550
679700985	Sandy Hill site inspection photos 6-27-2018	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4510543