

Inspection Photos  
Location Name: C F & I Corp. 1  
API: 05-081-05571



**Photo 1. Overview of location taken at entrance facing northeast.**



**Photo 2. No berm around produced water tanks. (Front view)**

Inspection Photos  
Location Name: C F & I Corp. 1  
API: 05-081-05571



**Photo 3. No berm around produced water tanks.  
(Rear view)**



**Photo 4. Standing adjacent to location boundary in  
same spot as Photo 3 was taken looking down into  
drainage gully that location borders.**