

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/06/2018

Submitted Date:

07/06/2018

Document Number:

689301467**FIELD INSPECTION FORM**
 Loc ID 334883 Inspector Name: Holtz, Darin On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**11 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|-------|---|--|
| Elsener, | | COGCC.inspections@caerus oilandgas.com | all Piceance inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------|-------------|
| 211281 | WELL | PR | 01/30/1996 | GW | 045-07040 | KRK 7-15 (07EB) | PR |
| 264556 | WELL | PR | 01/30/2003 | GW | 045-08921 | KRK 7-15C (07EB) | PR |
| 264557 | WELL | SI | 11/01/2017 | GW | 045-08922 | KRK 7-16B (07EB) | SI |
| 264558 | WELL | PR | 02/21/2003 | GW | 045-08923 | KRK 7-14A (07W) | PR |

General Comment:[Routine Field Inspection](#)

Location

| | | | |
|--------------------|--------|-------|--|
| Lease Road: | | | |
| Type | Access | | |
| comment: | | | |
| Corrective ActionL | | Date: | |

Overall Good: ☒

Emergency Contact Number:

Comment: 1-800-791-7691

Corrective Action:

Date:

Good Housekeeping:

| | | | |
|--------------------|--|-------|------------|
| Type | UNUSED EQUIPMENT | | |
| Comment: | Wellheads valve next to 045-08923, 7-14A Wellhead, see photo | | |
| Corrective Action: | Comply with Rule 603.f . | Date: | 08/06/2018 |
| Type | WEEDS | | |
| Comment: | Weeds on location, see photo | | |
| Corrective Action: | Comply with Rule 603.f . | Date: | 07/16/2018 |

Overall Good: ☐

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

| | | | |
|--------------------|-----------------|-------|--|
| Fencing/: | | | |
| Type | WELLHEAD | | |
| Comment: | Livestock gates | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------------------|-----|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Deadman # & Marked | # 6 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Plunger Lift | # 4 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Vertical Heated Separator | # 4 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Bird Protectors | # 1 | | |
| Comment: | | | |

| | | | |
|---------------------|-----|-------|--|
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| | | | | | | |
|--------------------|---------------------|----------|-----------|---------|--------|--|
| Contents | # | Capacity | Type | Tank ID | SE GPS | |
| CONDENSATE | 2 | 300 BBLs | STEEL AST | | , | |
| Comment: | Centralized Battery | | | | | |
| Corrective Action: | | | | | Date: | |

Paint

| | | |
|------------------|---------------|--|
| Condition | Adequate | |
| Other (Content) | Methanol Tank | |
| Other (Capacity) | 1000 gallons | |
| Other (Type) | | |

Berms

| | | | | | |
|--------------------|----------|---------------------|---------------------|-------------|--|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate | |
| Comment: | | | | | |
| Corrective Action: | | | | Date: | |

Venting:

| | | | |
|--------------------|----|--|-------|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

| Inspected Facilities | | | | | | | | | |
|-----------------------|---|-------|--|-------------|----------------------------|---------|----|---------------|----|
| Facility ID: | 211281 | Type: | WELL | API Number: | 045-07040 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Well Producing on plunger lift | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| | | | | | | | | | |
| Facility ID: | 264556 | Type: | WELL | API Number: | 045-08921 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Well Producing on plunger lift | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| | | | | | | | | | |
| Facility ID: | 264557 | Type: | WELL | API Number: | 045-08922 | Status: | SI | Insp. Status: | SI |
| Idle Well | | | | | | | | | |
| Purpose: | <input checked="" type="checkbox"/> Shut In | | <input type="checkbox"/> Temporarily Abandoned | | Reminder: EQUIPMENT ONSITE | | | | |
| Comment: | Well shut in at time of inspection | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| | | | | | | | | | |
| Facility ID: | 264558 | Type: | WELL | API Number: | 045-08923 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Well Producing on plunger lift | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |

| Environmental | |
|-----------------------------------|--|
| Spill/Remediation: | |
| Comment: | |
| Corrective Action: | Date: |
| Emission Control Burner (ECB): NO | |
| Comment: | |
| Pilot: | Wildlife Protection Devices (fired vessels): YES |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Culverts | | | | | | |
| Berms | | | | | | |
| Ditches | | | | | | |
| | | Compaction | | | | |
| | | Gravel | | | | |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------------------|---|
| 689301468 | Inspection Photo 689301468 | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4516128 |