

**HOAGLUND W-33-2 Pad**  
**Api# 05-045-06524**  
**Inspection # 689701580**



**Location photo.**

**HOAGLUND W-33-2 Pad**  
**Api# 05-045-06524**  
**Inspection # 689701580**



**Location photo. Weeds near well and meter shed.**



**HOAGLUND W-33-2 Pad**

**Api# 05-045-06524**

**Inspection # 689701580**



**Erosion of ruts on road to location.**

**HOAGLUND W-33-2 Pad**

**Api# 05-045-06524**

**Inspection # 689701580**



**Erosion of ruts on road to location.**



**HOAGLUND W-33-2 Pad**

**Api# 05-045-06524**

**Inspection # 689701580**



**Erosion rill on side of access road.**

**HOAGLUND W-33-2 Pad**  
**Api# 05-045-06524**  
**Inspection # 689701580**



**Trash and sediment build up at gated entrance of location.**



**HOAGLUND W-33-2 Pad**

**Api# 05-045-06524**

**Inspection # 689701580**



**Trash debris.**



**HOAGLUND W-33-2 Pad**

**Api# 05-045-06524**

**Inspection # 689701580**



**Trash debris.**