

**FORM  
INSP**Rev  
X/15

# State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/18/2018

Submitted Date:

07/04/2018

Document Number:

680602792**FIELD INSPECTION FORM**

Loc ID 326237 Inspector Name: ROY, CATHERINE On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 10464Name of Operator: CATAMOUNT ENERGY PARTNERS LLCAddress: 1801 BROADWAY #1000City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**4 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Recipient, Single		Inspections@catamountep.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216086	WELL	PR	11/05/1991	GW	067-07692	JAQUES 6-F	RI
454845	WELL	XX	04/23/2018		067-10018	Jaques 12	RI
454846	WELL	XX	04/23/2018		067-10019	Jaques 11	RI
454847	WELL	XX	04/23/2018		067-10020	Jaques 10	RI

**General Comment:**

This is a new construction and stormwater inspection. Any corrective actions not addressed from previous inspections are still applicable.

**Location Construction**

Location ID: 454845 CDP: \_\_\_\_\_

Comment: Topsoil stockpile was not identified during the inspection.

Corrective Action: Indicate to area reclamation specialist via field inspection response form, where topsoil is stockpiled for interim and final reclamation. Map or photo of stockpile location is needed.

Date: 07/13/2018

**Form 2A COAs:**

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Wildlife BMPs:**

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Comment:** Straw wattles, berms, and well pad drainage system are in place and appear to be functional. Additional stabilization measures are needed on well pad cut-slopes and bare soils as no protection is in place to prevent erosion from stormwater run-on, and erosion from exposed, soils.

**Corrective Action:** Stabilization measures such as wattles for run-on controls, tracking, mulching, etc. are needed on cut-slopes and exposed soils.

Date: 08/04/2018

**On Site Inspection (305):**Surface Owner Contact Information:

Name: \_\_\_\_\_

Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_

Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

**Inspected Facilities**

Facility ID: <u>216086</u>	Type: <u>WELL</u>	API Number: <u>067-07692</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>454845</u>	Type: <u>WELL</u>	API Number: <u>067-10018</u>	Status: <u>XX</u>	Insp. Status: <u>RI</u>
Facility ID: <u>454846</u>	Type: <u>WELL</u>	API Number: <u>067-10019</u>	Status: <u>XX</u>	Insp. Status: <u>RI</u>
Facility ID: <u>454847</u>	Type: <u>WELL</u>	API Number: <u>067-10020</u>	Status: <u>XX</u>	Insp. Status: <u>RI</u>

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401693631	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4514113">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4514113</a>
680602793	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4514112">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4514112</a>