

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/09/2018

Submitted Date:

07/11/2018

Document Number:

687902667**FIELD INSPECTION FORM**Loc ID 308582 Inspector Name: DURAN, JOHN On-Site Inspection ☐ 2A Doc Num: _____**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Operator Information:**OGCC Operator Number: 10084Name of Operator: PIONEER NATURAL RESOURCES USA INCAddress: 5205 N O'CONNOR BLVD STE 200City: IRVING State: TX Zip: 75039**Findings:**6 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Distribution, Pioneer	972-444-9001	COGCC.Inspections@pxd.co m	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
275076	WELL	PR	12/08/2004	GW	071-08268	SUNDOG 33-14	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Deadman # & Marked	# 4		
Comment:	3 Marked, 1 Unmarked		
Corrective Action:	Mark unmarked deadman.	Date:	08/11/2018
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Progressive Cavity	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	275076	Type:	WELL	API Number:	071-08268	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR - Calibration Report (5/2/17) (Photo).								
Corrective Action:	Need to update Calibration Report.							Date:	08/11/2018

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: NOPit ID: Lat: Long: Reference Point: Other: Length: Width: **Lining:**Liner Type: Liner Condition: Comment: Corrective Action: Date: c**Fencing:**Fencing Type: Fencing Condition: Comment: Corrective Action: Date: **Netting:**Netting Type: Netting Condition: Comment: Corrective Action: Date: Anchor Trench Present: Oil Accumulation: NO2+ feet Freeboard: YESComment: 30' x 60'Corrective Action: Date:

Permit:	Facility ID	Permit Num	Expiration Date
	280193	1140646	<input type="text"/>

Monitoring:	Monitoring Type	Comment
	Chain	Yellow

COGCC Comments

Comment	User	Date
SEE : Related Facility : Calibration Report. SEE : Equipment : deadman.	duranj	07/11/2018

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687902695	Expired Calibration Report	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4519760
687902696	Lease sign	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4519761

687902697	Well pad	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4519762
687902698	Downed Marker	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4519763