

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/05/2018

Submitted Date:

07/05/2018

Document Number:

687902605

**FIELD INSPECTION FORM**

Loc ID 307477 Inspector Name: DURAN, JOHN On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10084  
Name of Operator: PIONEER NATURAL RESOURCES USA INC  
Address: 5205 N O'CONNOR BLVD STE 200  
City: IRVING State: TX Zip: 75039

**Findings:**

- 6 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Distribution, Pioneer	972-444-9001	COGCC.Inspections@pxd.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
217714	WELL	PR	02/23/1998	GW	071-06493	MONTOYA 31-30	PR

**General Comment:**

**Location**

Overall Good:

**Signs/Marker:**

	Type WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:			
Corrective Action:		Date:	

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

					corrective date
Type: Vertical Separator	# 1				
Comment:					
Corrective Action:		Date:			
Type: Deadman # & Marked	# 3				
Comment:	2 Marked, 1 Unmarked				
Corrective Action:	Mark all deadman.	Date:	08/05/2018		
Type: Gas Meter Run	# 1				
Comment:					
Corrective Action:		Date:			
Type: Progressive Cavity	# 1				
Comment:					
Corrective Action:		Date:			

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 217714 Type: WELL API Number: 071-06493 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR - Last calibration on (04/24/17).

Corrective Action: Need to calibrate.

Date: 08/05/2018

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

Type: Produced Water      Lined: NO      Pit ID:      Lat:      Long:

Reference Point: \_\_\_\_\_      Other: \_\_\_\_\_      Length: \_\_\_\_\_      Width: \_\_\_\_\_

**Lining:**

Liner Type:      Liner Condition:

Comment:

Corrective Action

Date: c

**Fencing:**

Fencing Type:      Fencing Condition:

Comment:

Corrective Action

Date:

**Netting:**

Netting Type:      Netting Condition:

Comment:

Corrective Action

Date:

Anchor Trench Present:      Oil Accumulation: NO      2+ feet Freeboard: YES

Comment: 30' x 120' , U-shaped

Corrective Action

Date:

Monitoring:	Monitoring Type	Comment
	Chain	1 chain - red and yellow

**COGCC Comments**

Comment	User	Date
<u>SEE : Related Facility : Out of calibration. SEE : Equipment : deadman</u>	duranj	07/05/2018

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401694817	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4515179">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4515179</a>
687902606	Downed Marker	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4515155">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4515155</a>
687902607	Lease sign	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4515156">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4515156</a>
687902608	Well pad	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4515157">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4515157</a>

687902609

Calibration Report

<http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4515158>