

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/03/2018

Submitted Date:

07/05/2018

Document Number:

689401441

**FIELD INSPECTION FORM**

Loc ID 312548 Inspector Name: CONKLIN, CURTIS On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 53255  
Name of Operator: MARALEX RESOURCES INC  
Address: P O BOX 338  
City: IGNACIO State: CO Zip: 81137

**Findings:**

- 13 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Graves, Jim	(970) 858-8550	mrinc20@qwestoffice.net	Operation Manager
Hartman, Robert	(970) 244-3041	bhartman@blm.gov	Petroleum Engineer
Reid, Jordan	(970) 563-4000	maralextechjr@gmail.com	All Inspections
O'Hare, Mickey	(970) 563-4000/ (719) 429-3529	amohare@maralexinc.com	All Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221891	WELL	PR	03/01/2018	GW	077-08493	USA 1-18 JC	PR

**General Comment:**

This is a routine field inspection, any corrective actions not addressed from previous inspections are still applicable. This well is not listed in the AOC 1V-609

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Tank sign is not legible. See attached photo.		
Corrective Action:	Install sign to comply with rule 210	Date:	11/03/2018

**Emergency Contact Number:**

Comment:	Posted Emergency Contact Number 1-970-585-8550	
Corrective Action:		Date:

**Good Housekeeping:**

Type	OTHER		
Comment:	Vegetation and vegetation debris in tank containment and around equipment.		
Corrective Action:	Remove to comply with Rule 603.f	Date:	11/03/2018

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1		HEATED STEEL AST		,
Comment: See sign section of inspection.					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				
Comment: See housekeeping section of inspection.				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 221891 Type: WELL API Number: 077-08493 Status: PR Insp. Status: PR

**Producing Well**

Comment: [PR at time of inspection](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Stormwater erosion appears to be controlled on the location at this time.](#)

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

Type: Evaporation Lined: NO Pit ID: \_\_\_\_\_ Lat: \_\_\_\_\_ Long: \_\_\_\_\_

Reference Point: \_\_\_\_\_ Other: \_\_\_\_\_ Length: \_\_\_\_\_ Width: \_\_\_\_\_

**Lining:**

Liner Type: \_\_\_\_\_ Liner Condition: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date: c

**Fencing:**

Fencing Type: \_\_\_\_\_ Fencing Condition: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date: \_\_\_\_\_

**Netting:**

Netting Type: \_\_\_\_\_ Netting Condition: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date: \_\_\_\_\_

Anchor Trench Present: \_\_\_\_\_ Oil Accumulation: \_\_\_\_\_ 2+ feet Freeboard: \_\_\_\_\_

Comment: [No Facility ID for second pit on location.](#)

Corrective Action [Submit an eForm 15 Pit Report to update COGCC records with current information.](#) Date: 11/03/2018

Type: Evaporation Lined: NO Pit ID: 112451 Lat: 39.271180 Long: -108.372942

Reference Point: \_\_\_\_\_ Other: \_\_\_\_\_ Length: \_\_\_\_\_ Width: \_\_\_\_\_

**Lining:**

Liner Type: \_\_\_\_\_ Liner Condition: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date: c

**Fencing:**

Fencing Type: Livestock Fencing Condition: Adequate

Comment: \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date: \_\_\_\_\_

**Netting:**

Netting Type: \_\_\_\_\_ Netting Condition: \_\_\_\_\_

Comment:		Date:
Corrective Action		
Anchor Trench Present:                      Oil Accumulation: <u>NO</u> 2+ feet Freeboard:		
Comment:		Date:
Corrective Action		

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401694527	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4514941">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4514941</a>
689401442	USA 1-18 JC Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4514935">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4514935</a>