

Inspection Photos
Location Name: Fitzhugh #6
API: 05-007-05038



Stained soil beneath load out valve on AST.



Close up view of oil stained soil.

Inspection Photos
Location Name: Fitzhugh #6
API: 05-007-05038



Northwest corner of land farm treatment cell.



Southern edge of treatment cell.

Inspection Photos
Location Name: Fitzhugh #6
API: 05-007-05038



Fitzhugh #11 open excavation (behind stock panels).



Fitzhugh #7 open excavation.

Inspection Photos
Location Name: Fitzhugh #6
API: 05-007-05038



Fitzhugh #7 PA marker and well casing.



Fitzhugh #7 casing with fluids.

Inspection Photos
Location Name: Fitzhugh #6
API: 05-007-05038



Fitzhugh #7 with oil stained soil.



TA domestic gas supply well.

Inspection Photos
Location Name: Fitzhugh #6
API: 05-007-05038



Oil stained soil and well head at the Fitzhugh #6.



Oil staining downhill of the Fitzhugh #15.

Inspection Photos
Location Name: Fitzhugh #6
API: 05-007-05038



**PA marker for Fitzhugh #15 and abandoned flow line.
Fitzhugh #6 in the background.**




Fitzhugh #14 PA marker and abandoned flow line.

Inspection Photos
Location Name: Fitzhugh #6
API: 05-007-05038



PA marker for Fitzhugh #14 and abandoned flow line.



AST near Fitzhugh #6 labeled "Empty Not In Use".