

Inspection Photos
Location Name: Chavez #1
API: 05-007-06120



Chavez #1 pump jack and well head.



Stock tank with stained soil from excavation around well head.

Inspection Photos
Location Name: Chavez #1
API: 05-007-06120



**Removal of stained soil around well head has begun.
Excavation is approximately 2' deep currently.**

Sign has been added to tank battery for Chavez #2.