

### Photo log for Response to June 12, 2018 Inspection

COGCC conducted an inspection of the Lilli Unit 12-6 location (Location ID 327025) on June 12, 2018 (Document 684905506). During that inspection, COGCC made the following observation:

Storm Water: Stormwater erosion on NW corner of location. Install or repair required BMPs per Rule 1002.f.

Response: Noble repaired the erosion.

**COGCC – 6/12/18**



COGCC Photo 5: Stormwater erosion on NW side of location

**Noble Energy – 6/28/18**



Photo NBL1. Noble repaired the erosion.