

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/06/2018

Submitted Date:

07/06/2018

Document Number:

677900654**FIELD INSPECTION FORM**

Loc ID Inspector Name: On-Site Inspection ☐
 381172 Welsh, Brian 2A Doc Num: _____

Operator Information:OGCC Operator Number: 17180Name of Operator: CITATION OIL & GAS CORPAddress: 14077 CUTTEN RDCity: HOUSTON State: TX Zip: 77269**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:10 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Rogers, Bob	719-767-8851	brogers@cogc.com	
Elsom, Lee Ann	281-891-1577	lelsom@cogc.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
208539	WELL	SI	10/06/2014	OW	017-07474	MCCORMICK 31-3 1H	TA

General Comment:[Routine Inspection](#)

Location				
Lease Road:				
Type	Access			
comment:	Partially elevated gravel two track through pasture			
Corrective Action	L			Date:
Overall Good: <input checked="" type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:	Lease sign by unit			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:				
Corrective Action:				Date: _____
Good Housekeeping:				
Type	OTHER			
Comment:	Panels are laying around unit. Panels need to be installed around unit and wellhead or removed. Horsehead is stored next to unit			
Corrective Action:				Date:
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	PUMP JACK			
Comment:	Metal panels partially installed around unit and wellhead			
Corrective Action:				Date:
Equipment:				
Type: Prime Mover			# 1	corrective date
Comment:	Ford 6 cylinder motor			
Corrective Action:				Date:
Type: Ancillary equipment			# 1	
Comment:	Gas scrubber			
Corrective Action:				Date:
Type: Pump Jack			# 1	
Comment:	Lufkin unit. Horsehead removed at time of inspection			
Corrective Action:				Date:
Venting:				
Yes/No				

Comment:			
Corrective Action:		Date:	

Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 208539 Type: WELL API Number: 017-07474 Status: SI Insp. Status: TA**Producing Well**Comment: Central tank battery 4250' SW @ 38.855260/-102.884670

Corrective Action:

Date:

Idle WellPurpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: _____

Comment: Well is TA at time of inspection. Last production reported was Sept 2014. Well is past due for a MIT

Corrective Action:

Contact dnr_cogccengineering@state.co.us with resolution plan within 10 days of receipt of this inspectionDate: 07/16/2018

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401695712	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4516192