

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/06/2018

Submitted Date:

07/06/2018

Document Number:

687400466**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection ☐  
 319713 \_\_\_\_\_ Huck, Keith \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 95620Name of Operator: WESTERN OPERATING COMPANYAddress: 1165 DELAWARE STREET #200City: DENVER State: CO Zip: 80204**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**17 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Crumley, Tim	(970) 768-5659	tcrumley@comcast.net	
James, Steven D	(303) 893-2438	steve@westernoperating.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
201068	WELL	PR	10/01/2015	OW	001-06471	HOUGH 1-12	PR

**General Comment:**

## Location

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Good

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	There's a couple pieces of unused equipment sitting near by the pumpjack.		
Corrective Action:	90 days for unused equipment when machinery is required to remove the equipment. Comply with Rule 603.f . See attached pictures	Date:	10/04/2018

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Wire Fence		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	4 strand barbed wire		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	4 strand barbed wire		
Corrective Action:		Date:	

**Equipment:**

Type: Vertical Heater Treater	# 1		corrective date
Comment:	On burner stack sight glass or plug is missing.		

Corrective Action:	All stacks,vents, or other openings shall be equipped with screens or other appropriate equipment to prevent entry by wildlife,including migratory birds. per Rule 605.b.(7). See attached pictures		Date:	08/17/2018
Type: Other	# 1			
Comment:	Chemical Tank and pump at wellhead			
Corrective Action:			Date:	
Type: Other	# 1			
Comment:	Propane Tank			
Corrective Action:			Date:	
Type: Bird Protectors	# 1			
Comment:				
Corrective Action:			Date:	
Type: Pump Jack	# 1			
Comment:				
Corrective Action:			Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLS	STEEL AST		39.987270,-104.719240
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	300 BBLS	STEEL AST		,
Comment:	Both produced water tanks need painted				
Corrective Action:	Repair and paint tanks per Rule 804. See attached pictures				Date: 10/05/2018

**Paint**

Condition	Inadequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
------	----------	---------------------	---------------------	-------------

Inspector Name: Huck, Keith

Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:

**Venting:**

Yes/No	NO		
Comment:	NO AIRS NUMBER		
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**Facility ID: 201068 Type: WELL API Number: 001-06471 Status: PR Insp. Status: PR**Producing Well**Comment: PRCorrective Action: Date: **BradenHead**Comment: No Bradenhead visibleCorrective Action: Date: **COGCC Comments**

Comment	User	Date
<u>Routine Inspection</u>	huckk	07/06/2018

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401695724	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4516211">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4516211</a>
687400467	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4516210">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4516210</a>