

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/12/2018

Submitted Date:

07/13/2018

Document Number:

687902774**FIELD INSPECTION FORM**Loc ID 307395 Inspector Name: DURAN, JOHN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10084Name of Operator: PIONEER NATURAL RESOURCES USA INCAddress: 5205 N O'CONNOR BLVD STE 200City: IRVING State: TX Zip: 75039**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Distribution, Pioneer	972-444-9001	COGCC.Inspections@pxd.co m	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
217608	WELL	PR	05/01/2018	GW	071-06387	COTTONTAIL PASS UNIT 34-24	PR

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:  Date:

Overall Good: ☒

<b>Spills:</b>					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Progressive Cavity	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	217608	Type:	WELL	API Number:	071-06387	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR - Calibration Report (06/27/17) (Photos).								
Corrective Action:	Need to update Calibration Report.							Date:	08/13/2018

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<a href="#">SEE : Related Facility : Calibration Report</a>	duranj	07/13/2018

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687902775	Lease sign	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4522319">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4522319</a>
687902776	Calibration Report	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4522320">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4522320</a>
687902777	Well pad	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4522321">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4522321</a>
687902778	Calibration Report	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4522322">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4522322</a>
687902779	Calibration Report	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4522323">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4522323</a>