

# Inspection Photos

07/11/2018

Operator: FOUNDATION ENERGY  
MANAGEMENT LLC - 10112

Location ID: 327361

Inspection Doc. Number: 682503572  
Weld County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC

Inspection Photos  
Operator: FOUNDATION ENERGY MANAGEMENT LLC - 10112  
Location ID: 327361



**Photo 1:** Photo taken from the main access road, facing north. Photo shows scotch thistle has desiccated.



**Photo 2:** Photo taken from the main access road, east of the location. Previous inspection required management and removal of noxious weeds.

Photo shows Diffuse Knapweed (lighter, grey-green plants, white colored flowers) remains prevalent on location and access roads. Though there is evidence of herbicide, spraying does not appear to have been sufficient as many plants appear to be viable and have continued to mature/flower

Inspection Photos  
Operator: FOUNDATION ENERGY MANAGEMENT LLC - 10112  
Location ID: 327361



**Photo 3:** See comments under photo 2.



**Photo 4:** See comments under photo 2.

Inspection Photos  
Operator: FOUNDATION ENERGY MANAGEMENT LLC - 10112  
Location ID: 327361




**Photo 5:** Photo taken from the access road, north of the location facing south. See Comments under photo 2.



**Photo 6:** Photo taken from the west end of the location, facing south. See comments under photo 2.

Inspection Photos  
Operator: FOUNDATION ENERGY MANAGEMENT LLC - 10112  
Location ID: 327361



**Photo 7:** Photo taken from the west end of the location, facing south. See comments under photo 2.



**Photo 8:** Photo taken from the south end of the location, facing northeast. See comments under photo 2.

Inspection Photos

Operator: FOUNDATION ENERGY MANAGEMENT LLC - 10112

Location ID: 327361



**Photo 9:** Close up photo of Diffuse Knapweed observed on location. Photo shows that though Diffuse Knapweed (lighter, grey-green plants, white colored flowers) appears to have been sprayed w/ herbicide, spraying does not appear to have been sufficient as plant appear to be viable and have continued to mature/flower



**Photo 10:** See comment under photo 9.