



**Photo 1. View of the project area from the well pad entrance facing center. Area was recently mowed.**



**Photo 2. View of the southern portion of the project area from the entrance to the well pad facing westward. Well pad was mowed on this day.**





**Photo 3. View of the southeastern portion of the project area from the well pad entrance facing northeastward.**