

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/11/2018

Submitted Date:

07/11/2018

Document Number:

691300362**FIELD INSPECTION FORM**Loc ID 333033 Inspector Name: Kraich, Adam On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10110Name of Operator: GREAT WESTERN OPERATING COMPANY LLCAddress: 1001 17TH STREET #2000City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**11 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspections@gwogco.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
287398	WELL	TA	01/31/2018	OW	123-24312	GREAT WESTERN 27-13	TA
287400	WELL	SI	02/01/2018	OW	123-24313	GREAT WESTERN 27-14	SI
287403	WELL	SI	02/01/2018	OW	123-24315	GREAT WESTERN 27-24	SI
287404	WELL	SI	03/01/2017	OW	123-24316	GREAT WESTERN 27-53	SI

**General Comment:**

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type

TRASH

Comment: Old flow iron from previous wellheads laying next to wellheads. See photos.

Corrective Action: Remove trash to comply with rule 603.f

Date: 07/17/2018

Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type

TANK BATTERY

Comment:

Security chainlink

Corrective Action:

Date:

Type

WELLHEAD

Comment:

Security chainlink around all wellheads

Corrective Action:

Date:

**Equipment:**

corrective date

Type: Horizontal Heated Separator

# 2

Comment:

Corrective Action:

Date:

Type: Gas Meter Run

# 2

Comment:

Corrective Action:

Date:

Type: Plunger Lift

# 4

Comment:

Corrective Action:

Date:

Type: Emission Control Device

# 1

Comment:

Corrective Action:

Date:

**Tanks and Berms:**

Contents

#

Capacity

Type

Tank ID

SE GPS

PRODUCED WATER

1

OTHER

Comment: Tank appears to have no NFPA label. See photos.

Corrective Action:	Install NFPA label to comply with 210.d	Date:	09/09/2018
--------------------	---	-------	------------

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	150 BBLS	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:	Shares berms with production tanks				
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	3	300 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:	Shares berms with produced water tank				
Corrective Action:					Date:

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 287398 Type: WELL API Number: 123-24312 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: \_\_\_\_\_Comment: TA per document #40154061

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 287400 Type: WELL API Number: 123-24313 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_Comment: SI since 4/2017

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 287403 Type: WELL API Number: 123-24315 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_Comment: SI since 3/2017

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 287404 Type: WELL API Number: 123-24316 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_Comment: SI since 3/2017

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401700095	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4520445">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4520445</a>
691300363	Inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4520440">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4520440</a>