

FORM  
INSPRev  
X/15

**State of Colorado**  
**Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/10/2018

Submitted Date:

07/12/2018

Document Number:

688800212**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection   
312042 \_\_\_\_\_ Hughes, Jim \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**OGCC Operator Number: 10363Name of Operator: SCHUTZ\* RICHARD EAddress: PO BOX 66City: CHROMO State: CO Zip: 81128**Findings:**15 Number of Comments2 Number of Corrective Actions

- 
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Schutz, Sherry		schutzsherry@yahoo.com	
Schutz, Dick	(970) 264-4436	schutzre@yahoo.com	<a href="#">All Schutz Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
204998	WELL	PR	09/01/2017	OW	007-05038	FITZHUGH 6	EI
205003	WELL	PA		OW	007-05043	FITZHUGH 15	EI
205004	WELL	PA		OW	007-05044	FITZHUGH 14	EI
205091	WELL	DA		DA	007-05210	FITZHUGH 7	EI
450997	SPILL OR RELEASE	CL			-	Fitzhugh 15 15	EI

**General Comment:**

On July 10, 2018 COGCC SW EPS Jim Hughes conducted a follow up environmental field inspection of the Schutz Fitzhugh #6. This follow up inspection includes the #15, #7, and #11 as they relate to REM #10228. For the most recent field inspection report for this facility, please refer to document #688800081.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Sign mounted to stock panel enclosure around well head.		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	Sign mounted to stairway for AST, placard on tank.		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	AST near Fitzhugh #6 is reportedly not in service. Tank is labeled "Empty Not In Use"		
Corrective Action:			Date:

<b>Emergency Contact Number:</b>			
Comment:	Posted on location signs.		
Corrective Action:			Date: _____

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	
Crude Oil	WELLHEAD	<= 1 bbl	
Comment:	Stained soil around well head and beneath valve on nearby AST. Stained soil beneath valve on AST at tank battery.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.		Date: 08/13/2018

In Containment: No	
Comment:	
<input type="checkbox"/> Multiple Spills and Releases?	

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Stock panel enclosure around Fitzhugh #6 well head.		
Corrective Action:			Date:

<b>Equipment:</b>			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:

<b>Tanks and Berms:</b>					
Contents	#	Capacity	Type	Tank ID	SE GPS

CRUDE OIL	1	300 BBLs	STEEL AST		37.052782,-106.845979
Comment: Tank is no longer in service.					
Corrective Action:					Date:
<b>Paint</b>					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
<b>Berms</b>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment: No secondary containment. Tank is reportedly out of service. AST has been labeled "empty not in use".					
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		37.050851,-106.845992
Comment:					
Corrective Action:					Date:
<b>Paint</b>					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
<b>Berms</b>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment: No secondary containment for AST.					
Corrective Action: Repair or install berms or other secondary containment devices per Rule 605.a.(4). Corrective action taken from inspection document #674901720.					Date: 07/17/2017
<b>Venting:</b>					
Yes/No					
Comment:					
Corrective Action:					Date:
<b>Flaring:</b>					
Type					
Comment:					
Corrective Action:					Date:

**Inspected Facilities**

Facility ID: 204998 Type: WELL API Number: 007-05038 Status: PR Insp. Status: EI

Facility ID: 205003 Type: WELL API Number: 007-05043 Status: PA Insp. Status: EI

Facility ID: 205004 Type: WELL API Number: 007-05044 Status: PA Insp. Status: EI

Facility ID: 205091 Type: WELL API Number: 007-05210 Status: DA Insp. Status: EI

Facility ID: 450997 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

**Environmental**

**Waste Management:**

Type	Management	Condition	GPS (Lat) (Long)	
Oily Soil	Land Treatment	Adequate	37.050385	-106.845625
Comment	Land farmed material has been recently tilled. Ensure that containment berms are maintained to prevent storm water run off.			
Corrective Action				Date:

**Spill/Remediation:**

Comment:

Corrective Action:

Date: \_\_\_\_\_

Emission Control Burner (ECB): \_\_\_\_\_

Comment:

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention	In Process	

Comment: Stained soil beneath truck load out valve could be alleviated with a drip tray underneath.

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<p>On July 10, 2018 COGCC SW EPS Jim Hughes conducted a follow up environmental field inspection of the Schutz Fitzhugh #6. This follow up inspection includes the #15, #7, and #11 as they relate to REM #10228. For the most recent field inspection report for this facility, please refer to document #688800081.</p> <p>The land farmed material has recently been turned. Ensure that the containment berm is maintained to prevent storm water run-off. Continue working contents frequently to maximize exposure to the elements.</p> <p>The AST near the Fitzhugh #6 has been labeled "Empty Not In Use".</p>	hughesj	07/11/2018

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401700988	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4521215">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4521215</a>
688800213	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4521214">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4521214</a>