

GV 24-36
Api# 05-045-06631
Inspection # 689701623



Location photo

GV 24-36
Api# 05-045-06631
Inspection # 689701623



Land farm not being maintained.

GV 24-36
Api# 05-045-06631
Inspection # 689701623



Land farm not being maintained.

GV 24-36
Api# 05-045-06631
Inspection # 689701623



Channeling through location berm east of wells.

Channeling through location berm east of wells.

GV 24-36
Api# 05-045-06631
Inspection # 689701623



Sediment build up in ditch north wells.