

DOE 2-M-36  
Api# 05-045-06863  
Inspection # 689701629



Location photo

**DOE 2-M-36**  
**Api# 05-045-06863**  
**Inspection # 689701629**



**Unused flow lines in ditch on access road. Near gate between DOE 2-M-36 pad and GM 23-36 pad.**



DOE 2-M-36  
Api# 05-045-06863  
Inspection # 689701629



**Erosion of road and ditch.**

DOE 2-M-36  
Api# 05-045-06863  
Inspection # 689701629



Erosion on edge of location behind separators.



**DOE 2-M-36**  
**Api# 05-045-06863**  
**Inspection # 689701629**



**Sediment build up in check dam and washing around bale.**  
**39.48180 -108.05495**



**DOE 2-M-36**  
**Api# 05-045-06863**  
**Inspection # 689701629**



**Washing and erosion of drain run off. 39.48180 -108.05495**



**Washing and erosion of drain run off. 39.48180 -108.05495**

**DOE 2-M-36**  
**Api# 05-045-06863**  
**Inspection # 689701629**



**Sediment in ditch on main road just before access road. 39.47601 -108.06135**



DOE 2-M-36  
Api# 05-045-06863  
Inspection # 689701629



**Sediment in ditch at main and access road intersection.**



DOE 2-M-36  
Api# 05-045-06863  
Inspection # 689701629



Sediment in ditch at main and access road intersection.

DOE 2-M-36  
Api# 05-045-06863  
Inspection # 689701629



**Washing of road into ditch. Near GM 23-36 location in the back ground.**