

Interim Reclamation and Stormwater Inspection

July 16, 2018

Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC - #8960

Well API #: 05-123-35246

Inspection Document #: 682403798

Weld County, CO

NENW Section 24 T7N R62W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Crow Valley 7-62-24 #2H
Well API #: 05-123-35246



Photo 1. Photo taken from the eastern location on top of the topsoil stockpile, facing West. Appears the Operator has performed interim reclamation activities to reduce disturbance areas only needed for production operations. Photo illustrates the northern interim area and production area.

Inspection Photos
Location Name: Crow Valley 7-62-24 #2H
Well API #: 05-123-35246



07.16.2018 14:08

Photo 1. Photo taken from the eastern location on top of the topsoil stockpile, facing Southwest. Photo illustrates the southern interim area.

Inspection Photos
Location Name: Crow Valley 7-62-24 #2H
Well API #: 05-123-35246



Photo 3. Photo taken from the top of the topsoil stockpile. Photo illustrates weedy, annual vegetation (Kochia and Russian thistle) which has been recently mowed. Operator shall consider re-seeding the topsoil stockpile to help protect weed establishment per Rule 1002.c.

Inspection Photos
Location Name: Crow Valley 7-62-24 #2H
Well API #: 05-123-35246



Photo 4. Photo taken from the central interim area, facing West. Appears Operator recently mowed location. Operator shall continue to monitor and manage this site until the location meets Rule 1003 standards.

Inspection Photos
Location Name: Crow Valley 7-62-24 #2H
Well API #: 05-123-35246



Photo 5. Photo taken from the southeast production area, facing West. Photo illustrates a stormwater berm BMP full of cheatgrass. Operator shall remove cheatgrass, as this will migrate onto interim areas and negatively impact reclamation success. Also, this amount of dead plant material could pose as a fire safety hazard. Operator shall control and manage weeds throughout the entire location.



Photo 6. Photo taken from the weedhead, facing North. Unused equipment shall be removed per Rule 603.f.