



Photo 1. View of the project area from the northeastern edge facing center.



Photo 2. View of the eastern portion of the project area from the northeastern edge facing southward.



Photo 3. View of the northern portion of the project area from the northeastern edge facing northwestward.



Photo 4. View of the northeastern portion of the project area from the northeastern edge facing northward. Erosion is occurring along the access road.



Photo 5. View of facilities in the southern portion of the project area. Liquid is flowing through pipes here.



Photo 6. View of open pipe in the southern portion of the project area.



Photo 7. View of Russian knapweed (*Rhaponticum repens*) within the northeastern project area.