

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/16/2018

Submitted Date:

07/16/2018

Document Number:

689701615**FIELD INSPECTION FORM**Loc ID 334809 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**9 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Inspection, Terra TEP	970-285-9377	COGCCInspectionReports@terraep.com	
Colby, Lou		lou.colby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210765	WELL	PR	02/01/2018	GW	045-06523	FEDERAL MV-11-11	PR
273253	WELL	PR	07/07/2004	GW	045-10227	FEDERAL GM 421-11	PR
273254	WELL	SI	03/01/2018	GW	045-10226	FEDERAL GM 521-11	PR
273256	WELL	PR	12/28/2004	GW	045-10224	FEDERAL GM 321-11	PR

General Comment:

This is a routine field inspection, any corrective actions not addressed from previous inspections are still applicable.

Location**Lease Road:**

Type	Access		
comment:	Access road is rutted and rough at lower switchback where incline grade increases. 39.45850 -108.07752		
Corrective ActionL		Date:	

Overall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	970-285-9377	
Corrective Action:		Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Unused equipment and 200 bbl tank at wells.		
Corrective Action:	Comply with Rule 603.f .	Date:	08/17/2018

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	210765	Type:	WELL	API Number:	045-06523	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	273253	Type:	WELL	API Number:	045-10227	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	273254	Type:	WELL	API Number:	045-10226	Status:	SI	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	273256	Type:	WELL	API Number:	045-10224	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: See 4/26/18 inspection 680102936 corrective action.
 7/16/18 findings reflect previous inspection findings.
 Access road ditch washing and cutting and moving sediment. Washing of roadside at switch back 39.45850 -108.07752

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401704735	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4524917
689701616	Inspection 689701615 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4524915