

Inspection Photo
Federal RMF 534-19
API # 045-10237
Inspection # 689301574



Location Photo #1



Location Photo #2,

Inspection Photo
Federal RMF 534-19
API # 045-10237
Inspection # 689301574



Location Photo #3, Containment maintenance



Location Photo #4, Containment maintenance

Inspection Photo
Federal RMF 534-19
API # 045-10237
Inspection # 689301574



Location Photo #5, non legible battery sign

**Inspection Photo
Federal RMF 534-19
API # 045-10237
Inspection # 689301574**



Location Photo #6, slope erosion in SW corner, midslope



Location Photo #7, slope erosion in SW corner, midslope