

Inspection Photos
Location Name: USA Shaw 19
API: 05-081-60020



Photo 1. Overview of location taken at entrance facing southwest.

Inspection Photos
Location Name: USA Shaw 19
API: 05-081-60020



Photo 2. Wellhead. Oily bucket visible to left of wellhead.



Photo 3. Close-up of oily bucket at wellhead.

Inspection Photos
Location Name: USA Shaw 19
API: 05-081-60020



Photo 4. Fluid in cellar.



Photo 5. Stained gravel at loadout.