

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/23/2018

Submitted Date:

07/23/2018

Document Number:

689301566**FIELD INSPECTION FORM**

Loc ID 335109	Inspector Name: Holtz, Darin	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
Operator Information: OGCC Operator Number: <u>96850</u> Name of Operator: <u>TEP ROCKY MOUNTAIN LLC</u> Address: <u>PO BOX 370</u> City: <u>PARACHUTE</u> State: <u>CO</u> Zip: <u>81635</u>				Findings: <u>16</u> Number of Comments <u>2</u> Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Rocky, TEP		COGCCInspectionReports@terraep.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
257741	WELL	PR	06/20/2000	GW	045-07594	FEDERAL RMV 144-19	PR
272540	WELL	PR	11/20/2004	GW	045-10097	FEDERAL RWF 342-19	PR
272541	WELL	PR	11/22/2004	GW	045-10096	FEDERAL RWF 442-19	PR
286363	WELL	PR	08/24/2006	GW	045-12651	FEDERAL RWF 432-19	PR
286364	WELL	PR	08/24/2006	GW	045-12650	FEDERAL RWF 32-19	PR
286365	WELL	PR	08/24/2006	GW	045-12649	FEDERAL RWF 532-19	PR
286366	WELL	PR	08/24/2006	GW	045-12648	FEDERAL RWF 332-19	PR

General Comment:[Routine Field Inspection](#)

Location					
Lease Road:					
Type	Access				
comment:					
Corrective Action	L				Date:
Overall Good: <input checked="" type="checkbox"/>					
Emergency Contact Number:					
Comment:	1-970-285-9377				
Corrective Action:					Date:
Good Housekeeping:					
Type	DEBRIS				
Comment:	Wood stakes and plastic from an old waddles, East end of tank battery. see photo				
Corrective Action:	Comply with Rule 603.f .				Date: 08/02/2018
Overall Good: <input type="checkbox"/>					
Spills:					
Type	Area	Volume			
In Containment: No					
Comment: <input type="text"/>					
<input type="checkbox"/> Multiple Spills and Releases?					
Fencing/:					
Type	TANK BATTERY				
Comment:	Hog panel fencing				
Corrective Action:					Date:
Type	WELLHEAD				
Comment:	Hog panel fencing				
Corrective Action:					Date:
Type	SEPARATOR				
Comment:	Hog panel fencing				
Corrective Action:					Date:
Equipment:					
Type: Horizontal Heated Separator				# 10	corrective date
Comment:					
Corrective Action:					Date:
Type: Deadman # & Marked				# 3	
Comment:					
Corrective Action:					Date:
Type: Plunger Lift				# 0	
Comment:					
Corrective Action:					Date:

Type: Bird Protectors	# 5	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLs	STEEL AST		,
Comment:	Centralized Battery				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Inadequate
Comment:	Holes in containment liner near stairs, see photo			
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 605.a.(4).			Date: 08/30/2018

Venting:

Yes/No	NO	
Comment:		
Corrective Action:	Date:	

Flaring:

Type	
Comment:	

Corrective Action:		Date:	
--------------------	--	-------	--

Inspected Facilities									
Facility ID:	257741	Type:	WELL	API Number:	045-07594	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	272540	Type:	WELL	API Number:	045-10097	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	272541	Type:	WELL	API Number:	045-10096	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	286363	Type:	WELL	API Number:	045-12651	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	286364	Type:	WELL	API Number:	045-12650	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	286365	Type:	WELL	API Number:	045-12649	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	286366	Type:	WELL	API Number:	045-12648	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			

Environmental	
Spill/Remediation:	
Comment:	
Corrective Action:	Date:
Emission Control Burner (ECB): NO	
Comment:	
Pilot:	Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel				
Culverts						
Ditches						
		Compaction				
Berms						

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689301567	Inspection Photo 689301567	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4530961