

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/23/2018

Submitted Date:

07/23/2018

Document Number:

689301568

**FIELD INSPECTION FORM**

Loc ID 335176 Inspector Name: Holtz, Darin On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: PO BOX 370  
City: PARACHUTE State: CO Zip: 81635

**Findings:**

- 8 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Rocky, TEP		COGCCInspectionReports@terraep.com	<a href="#">All Inspections</a>
Colby, Lou		lou.colby@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211269	WELL	PR	12/01/1996	GW	045-07028	FEDERAL RMV 63-19	PR
277916	WELL	PR	05/07/2006	GW	045-10820	FEDERAL RWF 443-19	PR
277917	WELL	PR	07/01/2007	GW	045-10819	FEDERAL RWF 343-19	PR

**General Comment:**

[Routine Field Inspection](#)

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

Emergency Contact Number:			
Comment:	1-970-285-9377		
Corrective Action:			Date:

<b>Good Housekeeping:</b>			
Type	TRASH		
Comment:			
Corrective Action:			Date:
Type	WEEDS		
Comment:			
Corrective Action:			Date:
Type	DEBRIS		
Comment:			
Corrective Action:			Date:

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Hog panel fencing		
Corrective Action:			Date:

<b>Equipment:</b>			corrective date
Type: Plunger Lift	# 3		
Comment:			
Corrective Action:			Date:

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

<b>Flaring:</b>			
Type			

Comment:		
Corrective Action:	Date:	

**Inspected Facilities**

Facility ID: 211269 Type: WELL API Number: 045-07028 Status: PR Insp. Status: PR

**Producing Well**

Comment: Well Producing on plunger lift

Corrective Action:

Date:

Facility ID: 277916 Type: WELL API Number: 045-10820 Status: PR Insp. Status: PR

**Producing Well**

Comment: Well Producing on plunger lift

Corrective Action:

Date:

Facility ID: 277917 Type: WELL API Number: 045-10819 Status: PR Insp. Status: PR

**Producing Well**

Comment: Well Producing on plunger lift

Corrective Action:

Date:

**Environmental**

**Spill/Remediation:**

Comment:

Corrective Action:  Date:

Emission Control Burner (ECB): NO

Comment:

Pilot:  Wildlife Protection Devices (fired vessels):

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Seeding						
Berms						
Ditches						
		Gravel				
		Compaction				

Comment: [Storm water issue in location perimeter ditch on East side of location near the trees. see photos](#)

Corrective Action: [Install or repair required BMPs per Rule 1002.f.](#)

Date: 08/23/2018

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689301569	Inspection photo 689301569	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4530962">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4530962</a>