

Inspection Photos
Location Name: Dill Gulch 1-17
API: 05-107-06019



Photo 1. Overview of location taken at entrance facing northeast.



Photo 2. Tubing stored on location.

Inspection Photos
Location Name: Dill Gulch 1-17
API: 05-107-06019



Photo 3. Noxious weeds on location.



Photo 4. Stained soil at wellhead.

Inspection Photos
Location Name: Dill Gulch 1-17
API: 05-107-06019



Photo 5. Stained soil at pumpjack base.



Photo 6. Stained soil and noxious weeds at flowline connection.

Inspection Photos
Location Name: Dill Gulch 1-17
API: 05-107-06019



Photo 7. Stained soil and noxious weeds at flowline fitting.



Photo 8. Stained soil at tank base.

Inspection Photos
Location Name: Dill Gulch 1-17
API: 05-107-06019



Photo 9. Stained soil in tank berm.



Photo 10. Stained soil at tank base.

Inspection Photos
Location Name: Dill Gulch 1-17
API: 05-107-06019



Photo 11. Stained soil at tank base.



Photo 12. Stained soil at tank base.

Inspection Photos
Location Name: Dill Gulch 1-17
API: 05-107-06019



Photo 13. Stained soil at tank base.



Photo 14. Stained soil on tank berm perimeter.