

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/18/2018

Submitted Date:

07/18/2018

Document Number:

689701623**FIELD INSPECTION FORM**Loc ID _____ Inspector Name: _____ On-Site Inspection ☐
335010 _____ LONGWORTH, MIKE _____ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**9 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Inspection, Terra TEP	970-285-9377	COGCCInspectionReports@terraep.com	
Colby, Lou		lou.colby@state.co.us	
Spencer, Stan		stan.spencer@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210873	WELL	PR	11/09/1997	GW	045-06631	BARRETT ET AL GV 24-36	PR
260897	WELL	PR	07/14/2002	GW	045-07920	BARRETT GM 33-36	PR
290532	WELL	PR	05/10/2007	GW	045-14136	WILLIAMS GM 444-36	PR
290533	WELL	PR	05/10/2007	GW	045-14135	WILLIAMS GM 43-36	PR
290534	WELL	PR	05/31/2008	GW	045-14134	WILLIAMS GM 433-36	PR
290535	WELL	PR	01/12/2008	GW	045-14133	WILLIAMS GM 44-36	PR

General Comment:

This is a routine field inspection, any corrective actions not addressed from previous inspections are still applicable.
See 2/22/18 inspection # 680102702 Stormwater findings.

Inspected Facilities									
Facility ID:	210873	Type:	WELL	API Number:	045-06631	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	260897	Type:	WELL	API Number:	045-07920	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	290532	Type:	WELL	API Number:	045-14136	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	290533	Type:	WELL	API Number:	045-14135	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	290534	Type:	WELL	API Number:	045-14134	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	290535	Type:	WELL	API Number:	045-14133	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Fail					
Ditches	Fail					

Comment: [Channeling through location berm east of wells. Sediment build up in ditch north wells.](#)

Corrective Action: [Install or repair required BMPs per Rule 1002.f.](#)

Date: 08/20/2018

Pits: ☒ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Land farm not being maintained. "Contact COGCC EPS staff regarding Rule 906.c." by 7/27/18	longworm	07/18/2018

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401707230	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4527240
689701624	Inspection 689701623 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4527238