

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/18/2018

Submitted Date:

07/18/2018

Document Number:

689701625**FIELD INSPECTION FORM**Loc ID 334947 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Findings:**

- 7 Number of Comments
- 2 Number of Corrective Actions
- ☒ Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Colby, Lou		lou.colby@state.co.us	
Inspection, Terra TEP	970-285-9377	COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
256882	WELL	PR	07/18/2000	GW	045-07502	BARRETT GM 24-36	PR
290101	WELL	PR	04/11/2007	GW	045-13981	WILLIAMS GM 225-36	PR
290102	WELL	PR	04/11/2007	GW	045-13980	WILLIAMS GM 424-36	PR
290103	WELL	TA	12/31/2014	DSPW	045-13979	WILLIAMS GM 523-36	TA

**General Comment:**

This is a routine field inspection, any corrective actions not addressed from previous inspections are still applicable.  
See 2/22/18 inspection # 680102704

**Location**Overall Good: ☐**Signs/Marker:**

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 970-285-9377

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Deadman # & Marked	#		corrective date
Comment:	Unmarked deadman east of wells.		
Corrective Action:	Location is within a designated setback location, mark guy line anchors per Rule 604.c. (2)Q.		Date: 08/20/2018

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 256882 Type: WELL API Number: 045-07502 Status: PR Insp. Status: PR**Producing Well**Comment: Producing well

Corrective Action:

Date:

Facility ID: 290101 Type: WELL API Number: 045-13981 Status: PR Insp. Status: PR**Producing Well**Comment: Producing well

Corrective Action:

Date:

Facility ID: 290102 Type: WELL API Number: 045-13980 Status: PR Insp. Status: PR**Producing Well**Comment: Producing well

Corrective Action:

Date:

Facility ID: 290103 Type: WELL API Number: 045-13979 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In☒ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Channeling and erosion of the edge of ditch. Uphill access of location has ruts washing. Ditch on access needs maintained.

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 08/20/2018

Pits: ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401707231	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4527241">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4527241</a>
689701626	Inspection 689701625 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4527239">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4527239</a>