

TR 513-26-597
API# 05-045-18339
Inspection# 689701671



Location photo.

TR 513-26-597
API# 05-045-18339
Inspection# 689701671



Unused equipment.

TR 513-26-597
API# 05-045-18339
Inspection# 689701671



Tank thief hatch is open. Berm has been knocked down.

TR 513-26-597
API# 05-045-18339
Inspection# 689701671



Metal secondary containment is damaged.

TR 513-26-597
API# 05-045-18339
Inspection# 689701671



Unused 2" riser at TR 43-27-597



Unused 2" riser.