

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/17/2018

Submitted Date:

08/01/2018

Document Number:

689701622**FIELD INSPECTION FORM**Loc ID 334580 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
- 
- ☒
- FOLLOW UP INSPECTION REQUIRED
- 
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Findings:**8 Number of Comments2 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Inspection, Terra TEP	970-285-9377	COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211483	WELL	PR	08/12/2005	GW	045-07243	BOSELY SG 43-22	PR
279733	WELL	PR	07/09/2006	GW	045-11074	BOSELY SG 543-22	PR
279734	WELL	PR	06/29/2006	GW	045-11075	BOSELY SG 443-22	PR
279735	WELL	PR	07/06/2006	GW	045-11076	BOSELY SG 343-22	PR

**General Comment:**Follow up to 04/13/2018 inspection # 689701279  
Corrective actions have not been completed.

**Location**Overall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	Write in tank volume on tank label not legible.		
Corrective Action:	Install sign to comply with Rule 210.e.	Date:	06/22/2018

**Emergency Contact Number:**

Comment:	970-285-9377		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	211483	Type:	WELL	API Number:	045-07243	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	279733	Type:	WELL	API Number:	045-11074	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	279734	Type:	WELL	API Number:	045-11075	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	279735	Type:	WELL	API Number:	045-11076	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Comment: Just before location washing of road cutting into v ditch. 39.42140 108.08775. Sediment build up in culvert. 39.42103 108.08820 Additional findings Channeling through location berm and sediment build up behind location berm.						
Corrective Action: Install or repair required BMPs per Rule 1002.f.						Date: 05/18/2018
<b>Pits:</b> <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT						

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689701632	Inspection 689701622 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4540235">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4540235</a>