

Inspection Photos

07/31/2018

Operator: WESTERN OPERATING COMPANY -
95620

Location ID: 312292

Inspection Doc. Number: 682503670
Logan County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: WESTERN OPERATING COMPANY - 95620
Location ID: 312292



Photo 1: Photos 1-2 taken from the northeast end of the pumpjack, facing northeast to east. Photos show interim areas of the location have been regraded and appears to have been reseeded. However, no stabilization or stormwater and erosion control BMPs have been installed per the corrective actions.



Photo 2:

Inspection Photos
Operator: WESTERN OPERATING COMPANY - 95620
Location ID: 312292



Photo 3: Photo taken from the central area of the location facing south. Photo shows tractor and seeding equipment on location.



Photo 4: Photo taken from the central interim areas of the location (see photos 1-2). Photos show interim areas of the location have been regraded and appears to have been reseeded. However, no stabilization or stormwater and erosion control BMPs have been installed per the corrective actions.

Inspection Photos
Operator: WESTERN OPERATING COMPANY - 95620
Location ID: 312292



Photo 5: Photo taken from the south end of the location, facing south. Photos show interim areas of the location have been regraded and appears to have been reseeded. However, no stabilization or stormwater and erosion control BMPs have been installed per the corrective actions.



Photo 6: Photo taken from the south end of the location, facing southwest. Photos show interim areas of the south and east of the pit have been regraded and appears to have been reseeded. However, no stabilization or stormwater and erosion control BMPs have been installed per the corrective actions. Photos show erosion degradation has been allowed to continue on the slope.

Inspection Photos
Operator: WESTERN OPERATING COMPANY - 95620
Location ID: 312292



Photo 7: Continued from photo 6. Photo taken from the slopes east of the pit, facing south. Photo shows operator appears to have regraded and reseeded the disturbance areas. However, no stabilization or stormwater and erosion control BMPs have been installed per the corrective actions. Photos show erosion degradation has been allowed to continue on the slope.



Photo 8: See comments under photo 7.

Inspection Photos
Operator: WESTERN OPERATING COMPANY - 95620
Location ID: 312292



Photo 9: Photo taken from the southeast corner of the pit, facing south. See comments under photo 7.



Photo 10: Photo taken from the southwest corner of the pit, facing south. Photos show interim areas of the south and east of the pit have been regraded and appears to have been reseeded. However, no stabilization or stormwater and erosion control BMPs have been installed per the corrective actions

Inspection Photos
Operator: WESTERN OPERATING COMPANY - 95620
Location ID: 312292



Photo 11: Photo taken from the southwest corner of the pit, facing south. Photos show interim areas of the south and east of the pit have been regraded and appears to have been reseeded. However, no stabilization or stormwater and erosion control BMPs have been installed per the corrective actions



Photo 12: Photo taken from the southwest corner of the pit, facing north. See comments under photo 7.

Inspection Photos
Operator: WESTERN OPERATING COMPANY - 95620
Location ID: 312292



Photo 13: Photo taken from the southwest corner of the pit, facing west. Photos show interim areas of the south and east of the pit have been regraded and appears to have been reseeded. However, no stabilization or stormwater and erosion control BMPs have been installed per the corrective actions



Photo 14: Photo shows operator appears to have regraded and reseeded the disturbance areas. However, no stabilization or stormwater and erosion control BMPs have been installed per the corrective actions. Photos show erosion degradation has been allowed to re-occur on the slope.

Inspection Photos
Operator: WESTERN OPERATING COMPANY - 95620
Location ID: 312292



Photo 15: Photo taken from the access road gate, north of the location facing south. Photo shows stormwater erosion has cut underneath the cattle guard. This needs to be repaired and stabilized.



Photo 16: Photo taken from the access road gate, north of the location facing south. Photo shows stormwater erosion has cut underneath the cattle guard. This needs to be repaired and stabilized.