

# Inspection Photos

07/31/2018

Operator: WESTERN OPERATING COMPANY -  
95620

Location ID: 312291

Inspection Doc. Number: 682503672  
Logan County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC

Inspection Photos  
Operator: WESTERN OPERATING COMPANY - 95620  
Location ID: 312291



**Photo 1:** Photos 1-2 taken from the northeast end of the pit, facing east. Photos show interim areas of the location have been regraded and appears to have been reseeded. However, no stabilization, or stormwater and erosion control BMPs have been installed per the corrective actions. Photos show erosion degradation has been allowed to continue on the slope.



**Photo 2:** 6 foot measuring stick for reference.

Inspection Photos  
Operator: WESTERN OPERATING COMPANY - 95620  
Location ID: 312291



**Photo 3:** Photo taken from the northeast corner of the pit, facing south. Photos show interim areas of the location have been regraded and appears to have been reseeded. However, no stabilization, or stormwater and erosion control BMPs have been installed per the corrective actions. Photos show erosion degradation has been allowed to continue on the slope.



**Photo 4:** Photo taken from east of the pit, facing northwest. See comments under photo 3.

Inspection Photos  
Operator: WESTERN OPERATING COMPANY - 95620  
Location ID: 312291



**Photo 5:** Continued from photo 4. Photo shows sediment deposition caused by stormwater erosion from the slopes.



**Photo 6:** Photo taken from the east end of the pit, facing north. See comments under photo 3.

Inspection Photos  
Operator: WESTERN OPERATING COMPANY - 95620  
Location ID: 312291



**Photo 7:** Photo taken from the east end of the pit, facing west. See comments under photo 3.



**Photo 8:** Photo taken from the southeast end of the pit, facing north west. Photo shows erosion degradation has continued from the pit with sediment being transported off location and onto the interim areas. Additionally, interim areas of the location have been regraded and appears to have been reseeded. However, no stabilization, or stormwater and erosion control BMPs have been installed per the corrective actions. Photos show erosion degradation has been allowed to continue on the slopes.



**Photo 9:** See photo 8.



**Photo 10:** Photo taken from the southwest corner of the pit, facing west. Photo show interim areas of the location have been regraded and appears to have been reseeded. However, no stabilization, or stormwater and erosion control BMPs have been installed per the corrective actions. Photo show erosion degradation has been allowed to continue on the slope.

Inspection Photos  
Operator: WESTERN OPERATING COMPANY - 95620  
Location ID: 312291



**Photo 11:** Photo taken from the southwest of the pit, facing northeast. See comments under photo 10.



**Photo 12:** Photo taken from the west end of the pit, facing northeast. See comments under photo 10.

Inspection Photos  
Operator: WESTERN OPERATING COMPANY - 95620  
Location ID: 312291



**Photo 13:** Photo taken from the west end of the location. Photo work appears to have been conducted to repair gulley erosion, however no stabilization controls have been implemented and erosion degradation has been allowed to continue.



**Photo 14:** Photo taken from the west end of the location, facing east. See comments under photo 13.



**Photo 15:** Photo taken from the south end of the facilities, facing north. Photo shows barrel laying along fence. This is improper materials management, barrel needs to be placed in secondary containment, or removed and properly stored.