

Inspection Photos
Location Name: Federal Sandwash 2-1
API: 05-081-06792



Photo 1. Overview of location taken at entrance facing east.



Photo 2. Corrosion along tank bottom.

Inspection Photos
Location Name: Federal Sandwash 2-1
API: 05-081-06792



Photo 3. Close-up of corrosion with holes formed.



Photo 4. Close-up of corrosion.

API: 05-081-06792



Photo 5. Incorrect emergency contact information on location signs.

Photo 6. Incorrect emergency contact information on location signs.