

Inspection Photos
Location Name: Okes 5-6
API: 05-081-06798



Photo 1. Overview of location taken at entrance facing east.



Photo 2. Incorrect emergency contact information on location signs.

Inspection Photos
Location Name: Okes 5-6
API: 05-081-06798



Photo 3. Incorrect emergency contact information on location signs.



Photo 4. Incorrect emergency contact information on location signs.

Inspection Photos
Location Name: Okes 5-6
API: 05-081-06798



Photo 5. Hole in tank bottom.



Photo 6. Close-up of hole in tank bottom.