

Inspection Photos

08/02/2018

Operator: OILFIELD SALVAGE & SERVICE CO -
65550

Location ID: 311709

Inspection Doc. Number: 682503696
Adams County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: OILFIELD SALVAGE & SERVICE CO - 65550
Location ID: 311709



Photo 1: Photo taken from the northwest end of the fenced spill area facing east. Previous inspections required operator to perform reclamation and stormwater management (properly select and install site specific stormwater and sediment control BMPs). Reclamation activities were previously conducted, however it was documented that no controls to stabilize the seeded soil were implemented per the corrective action, and that the seeded soil was at risk to wind and stormwater erosion. Photo shows that straw wattles improperly installed and insufficient, and that stormwater erosion has been allowed to continue. Additionally, photo also shows that vegetation has failed to germinate and establish on the location.



Photo 2: Photo taken from the northwest end of the fenced spill area facing southeast. See comments under photo 1.

Inspection Photos
Operator: OILFIELD SALVAGE & SERVICE CO - 65550
Location ID: 311709



Photo 3: Photo taken from the location. Photo shows that straw wattles improperly installed and insufficient, and that stormwater erosion has been allowed to continue. See comments under photo 1.



Photo 4: Photo taken from the location, facing north. Photo shows that straw wattles improperly installed and insufficient, and that stormwater erosion has been allowed to continue. See comments under photo 1. Six (6) foot measuring stick for reference.

Inspection Photos
Operator: OILFIELD SALVAGE & SERVICE CO - 65550
Location ID: 311709



Photo 5: Photo taken from the location, facing south. Photo shows that straw wattles improperly installed and insufficient, and that stormwater erosion has been allowed to continue. See comments under photo 1. Six (6) foot measuring stick for reference.



Photo 6: Photo taken from the location, facing north. Photo shows that straw wattles improperly installed and insufficient, and that stormwater erosion has been allowed to continue. See comments under photo 1. Six (6) foot measuring stick for reference.

Inspection Photos
Operator: OILFIELD SALVAGE & SERVICE CO -
65550



Photo 5: Photo taken from the location, facing north. Photo shows that straw wattles improperly installed and insufficient, and that stormwater erosion has been allowed to continue. See comments under photo 1. Six (6) foot measuring stick for reference.