

Inspection Photos

08/02/2018

Operator: WESTERN OPERATING COMPANY -
95620

Location ID: 319767

Inspection Doc. Number: 682503700
Adams County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: WESTERN OPERATING COMPANY - 95620
Location ID: 319767



Photo 1: Photo taken from the northeast corner of the location, facing south. Photo shows erosion degradation on the location. Photo also shows the location has not be recontoured/regraded in accordance to 1004.a



Photo 2: Photo taken from the northeast corner of the location, facing southwest. See comments under photo 1.

Inspection Photos
Operator: WESTERN OPERATING COMPANY - 95620
Location ID: 319767



Photo 3: Photo taken from the northeast corner of the location, facing west. See comments under photo 1.



Photo 4: Photo taken from the west end of the location, facing southwest. Photo shows no reclamation activities, including compaction alleviation, recontouring/regrading and revegetation appear to have been conducted on the access road.

Inspection Photos
Operator: WESTERN OPERATING COMPANY - 95620
Location ID: 319767



Photo 5: Photo taken from the west end of the location, facing southwest. Photo shows no reclamation activities, including compaction alleviation, recontouring/regrading and revegetation appear to have been conducted on the access road.



Photo 6: Photo taken from the west end of the location, facing southeast. Photo shows no reclamation activities, including compaction alleviation, recontouring/regrading and revegetation appear to have been conducted on the access road.

Inspection Photos
Operator: WESTERN OPERATING COMPANY - 95620
Location ID: 319767



Photo 7: Photo taken from the west end of the location, facing north. Photos 7-8 provide overview of the location



Photo 8: Photo taken from the west end of the location, facing east.

Inspection Photos
Operator: WESTERN OPERATING COMPANY - 95620
Location ID: 319767



Photo 9: Photo taken from the west end of where the well was location. Photo shows reclamation activities only appear to have been conducted in the immediate areas of the well (fenced area).



Photo 10: Photo taken from the south end of the location, facing south. Photo shows a shallow gully that has formed from stormwater runoff on the slopes of the location.

Inspection Photos
Operator: WESTERN OPERATING COMPANY - 95620
Location ID: 319767



Photo 11: Photo taken from the fenced area of the well, facing west. Photo shows compaction alleviation and revegetation activities appear to have been conducted in the area of the well. Inspector was able to easily penetrate the top 8-10 inches of the soil with a shovel.



Photo 12: Photo taken from outside of the fenced area of the well, facing west. Photo shows compaction alleviation and revegetation activities DO NOT appear to have been conducted in the remaining location. Inspector was able to penetrate the top couple of inches of the soil with a shovel; compaction concerns evident.

Inspection Photos
Operator: WESTERN OPERATING COMPANY -
95620



Photo 13: Photo taken from the adjacent reference area. Photo shows inspector tested the soils in the reference area for compaction to compare to the disturbed areas of the location. Inspector was able to easily penetrate the top 8-10 inches of the soil with a shovel.

Inspection Photos
Operator: WESTERN OPERATING COMPANY -
95620



Photo 5: Photo taken from the east end of the location, facing southwest. Photo shows no reclamation activities, including compaction alleviation, recontouring/regrading and revegetation appear to have been conducted on the access road.