


**Inspection Photo
COX 33-1 (B33NE)
API # 045-13388
Inspection # 689301681**



Location Photo #1



Location Photo #2, Oil stained rock near separators.

**Inspection Photo
COX 33-1 (B33NE)
API # 045-13388
Inspection # 689301681**



Location Photo #3, Stained rock in tank containment.



Location Photo #4, Stained rock in tank containment.

**Inspection Photo
COX 33-1 (B33NE)
API # 045-13388
Inspection # 689301681**



Location Photo #5, Stained rock in tank containment.



Location Photo #6, Hole in secondary containment.