

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/01/2018

Submitted Date:

08/01/2018

Document Number:

689801485**FIELD INSPECTION FORM**
 Loc ID 313133 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 3975Name of Operator: ARGALI EXPLORATION COMPANYAddress: PO BOX 416City: RANGELY State: CO Zip: 81648**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**9 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
General, Contact		argaliexplorationcompany@gmail.com	
Leonard, Mike		mike.leonard@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
259533	WELL	SI	05/01/2018	GW	081-07045	VISINTAINER FEDERAL 1-12	WK

General Comment:

Routine FIU inspection and MIT witness.

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Sign not posted or information inaccurate at well(s) or battery.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	09/03/2018

Emergency Contact Number:

Comment: Emergency contact information incorrect on location signs.

Corrective Action: Install sign to comply with Rule 210.

Date: 09/03/2018

Good Housekeeping:

Type	WEEDS		
Comment:	Noxious weeds on location.		
Corrective Action:	Comply with Rule 603.f .	Date:	08/15/2018

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	

Equipment:

Type: Bird Protectors	#		corrective date
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		

Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:	40.67898, -107.56012		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	40.67898, -107.56012		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	400 BBLS	STEEL AST		40.678830,-107.560280	
Comment:	Gauge hatch open.					
Corrective Action:	Close gauge hatches when not accessing tank per Rule 605.a.(9).					Date: 08/02/2018

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			Adequate
Comment:				
Corrective Action:				
		Date:		

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	259533	Type:	WELL	API Number:	081-07045	Status:	SI	Insp. Status:	WK
Workover									
Comment:	Inspector on location to witness MIT to return well to production. Casing at 455 psi at start of test and 480 after 15 minutes. Gain of 25 psi. Test passed.								
Corrective Action:					Date:				

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [No apparent soil migration; erosion or soil movement.](#)

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401722028	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4541208
689801486	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4541201