

Inspection Photos

Location Name: Lake Fox Water Storage Facility

Facility ID: #149016

Inspection Date: August 1, 2018



Photo #1 – View of damaged safety fence, flowline manifold, and freshwater pit from SW corner of location.



Photo #2 – Damaged shed and insulated flowline manifold located at SW corner of pit. Note tangled wiring draped on top of flowline manifold.



Inspection Photos

Location Name: Lake Fox Water Storage Facility

Facility ID: #149016

Inspection Date: August 1, 2018



Photo #3 – Damaged safety fence located southwest of pit.



Photo #4 – Damaged pit liner, liner debris, and pipeline riser located at SW corner of pit.



Inspection Photos

Location Name: Lake Fox Water Storage Facility

Facility ID: #149016

Inspection Date: August 1, 2018



Photo #5 – Holes in pit liner along anchor trench (1).



Photo #6 - Holes in pit liner along anchor trench (2).



Inspection Photos

Location Name: Lake Fox Water Storage Facility

Facility ID: #149016

Inspection Date: August 1, 2018



Photo #7 - Holes in pit liner along anchor trench (3).



Photo #8 – Holes (and vegetation) in pit liner along anchor trench (4).



Inspection Photos
Location Name: Lake Fox Water Storage Facility
Facility ID: #149016
Inspection Date: August 1, 2018



Photo #9 – Holes observed in pit liner along base of pit.



Photo #10 – Wood debris, vegetation, and scraps of liner located inside of pit.