



**Photo 1. View of the project area from the eastern corner facing center.**



**Photo 2. View of the southeastern portion of the project area from the eastern corner facing southwestward.**





**Photo 3. View of Russian knapweed (*Rhaponticum repens*) in the southeastern portion of the project area. Approximately 100 individuals observed.**





**Photo 4. View of area along the access road where it appears that stormwater flows over the road and erodes the road surface and shoulders, depositing debris downstream.**





**Photo 5. View of another area along the access road where stormwater flows are eroding the road. Gravel is washed off of the road and deposited downstream.**





**Photo 6. View of another area along the access road where stormwater is eroding the road surface.**