



Photo 1. View of the project area from the western corner facing center.



Photo 2. View of the southwestern portion of the project area from the western corner facing southeastward.



Photo 3. View of the northwestern portion of the project area from the western corner facing northeastward.



Photo 4. View of the northeastern cut-slope. Vegetation is progressing, but rilling is occurring here.



Photo 5. View of trash/debris on the well pad.



Photo 6. View of more trash/debris in the southeastern cut-slope.



Photo 5. View unused equipment within the project area.