

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/13/2018

Submitted Date:

08/15/2018

Document Number:

689801538**FIELD INSPECTION FORM**
 Loc ID 313190 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 97810Name of Operator: EOG Y RESOURCES INCAddress: 105 SOUTH 4TH STCity: ARTESIA State: NM Zip: 88210**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☐ FOLLOW UP INSPECTION REQUIRED☒ NO FOLLOW UP INSPECTION REQUIRED**Findings:**7 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|-------------------|--------------|-----------------------------------|---------|
| Allman, Stephanie | 307-382-4005 | stephanie_allman@eogresources.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------|-------------|
| 271331 | WELL | SI | 12/29/2010 | GW | 081-07173 | BAKERS PEAK UNIT 2 | SI |

General Comment:

Routine FIU inspection.

LocationOverall Good: ☒

| | | | |
|----------------------|---|-------|------------|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Sign or label not posted or information inaccurate on tanks or containers. No NFPA diamond on produced water tank. | | |
| Corrective Action: | Install sign to comply with Rule 210.d. | Date: | 10/15/2018 |

Emergency Contact Number:

Comment:

Corrective Action: Date:

Good Housekeeping:

| | | | |
|--------------------|---|-------|------------|
| Type | UNUSED EQUIPMENT | | |
| Comment: | 3 - 3", 4 - 2", and 2 - 1/2" steel risers not marked for abandonment or LOTO at 40.91593, -107.55100. | | |
| Corrective Action: | Comply with Rule 603.f . | Date: | 08/16/2018 |

Overall Good: ☐

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment: ☐ Multiple Spills and Releases?

| | | | |
|--------------------|--------------|-------|--|
| Fencing/: | | | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | TANK BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------------------|----------------------|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Bird Protectors | # | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Horizontal Heater Treater | # 1 | | |
| Comment: | 40.91627, -107.55131 | | |

| | | | |
|--------------------------|----------------------|-------|--|
| Corrective Action: | | Date: | |
| Type: Compressor | # | | |
| Comment: | 40.91611, -107.55104 | | |
| Corrective Action: | | Date: | |
| Type: Deadman # & Marked | # 4 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| CONDENSATE | 1 | 400 BBLS | STEEL AST | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Earth | Adequate | | | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|------------------|---------|-----------------------|
| PRODUCED WATER | 1 | 400 BBLS | HEATED STEEL AST | | 40.916330,-107.551720 |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Earth | Adequate | | | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | | |
|----------|----|--|
| Yes/No | NO | |
| Comment: | | |

| | | | |
|--------------------|--|-------|--|
| Corrective Action: | | Date: | |
| Flaring: | | | |
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| Inspected Facilities | | | | | | | | | |
|--|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 271331 | Type: | WELL | API Number: | 081-07173 | Status: | SI | Insp. Status: | SI |
| Idle Well | | | | | | | | | |
| Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____ | | | | | | | | | |
| Comment: <input type="text" value="Last MIT 12/10/2014."/> _____ | | | | | | | | | |
| Corrective Action: <input type="text"/> _____ Date: _____ | | | | | | | | | |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|--|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |
| <p>Comment: No apparent soil migration; erosion or soil movement.</p> <p>Corrective Action: <input type="text"/></p> <p>Date: <input type="text"/></p> | | | | | | |
| <p>Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT</p> | | | | | | |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------|---|
| 689801546 | Inspection Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4552391 |