

Inspection Photos

08/14/2018

Operator: RUNNING FOXES PETROLEUM INC -
10221

Location ID: 309613

Inspection Doc. Number: 682503720
Lincoln County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: RUNNING FOXES PETROLEUM INC - 10221
Location ID: 309613



Photo 1: Photo taken from the location, facing north. Photo shows vegetation over the reclamation area.



Photo 2: Photo taken from the location, facing east. Photo shows vegetation over the reclamation area.

Inspection Photos
Operator: RUNNING FOXES PETROLEUM INC - 10221
Location ID: 309613



Photo 3: Photo taken from the location, facing south. Photo shows vegetation over the reclamation area.



Photo 4: Photo taken from the location, facing west. Photo shows vegetation over the reclamation area.

Inspection Photos
Operator: RUNNING FOXES PETROLEUM INC - 10221
Location ID: 309613



Photo 5: Photo taken from what appears to have been the former access road, facing northeast.



Photo 6: Photo taken from the location, facing north. Photo shows the starting point for the **DISTURBANCE AREA** transect.

Inspection Photos
Operator: RUNNING FOXES PETROLEUM INC - 10221
Location ID: 309613



Photo 7: Photo taken from the 50th point of the **DISTURBANCE AREA** transect, facing east.



Photo 8: Photo taken from the 50th point of the **DISTURBANCE AREA** transect, facing west.

Inspection Photos

Operator: RUNNING FOXES PETROLEUM INC - 10221

Location ID: 309613



Photo 9: Photo taken from the 50th point of the **DISTURBANCE AREA**.



Photo 10: Photo taken from the location, facing south. Photo shows the end point for the **DISTURBANCE AREA** transect.

Inspection Photos
Operator: RUNNING FOXES PETROLEUM INC - 10221
Location ID: 309613



Photo 11: Photo taken from the adjacent reference, facing east. Photo shows the starting point for the **REFERENCE AREA** transect.



Photo 12: Photo taken from the 50th point of the **REFERENCE AREA** transect, facing South.

Inspection Photos
Operator: RUNNING FOXES PETROLEUM INC - 10221
Location ID: 309613



Photo 13: Photo taken from the 50th point of the **REFERENCE AREA** transect, facing North.



Photo 14: Photo taken from the 50th point of the **REFERENCE AREA** transect.



Photo 15: Photo taken from the adjacent reference, facing west. Photo shows the end point for the **REFERENCE AREA** transect.