

Inspection Photos

Operator: SG Interests

API: 05-051-06152

Date: 7/25/2018



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the western portion of the project area from the northwestern corner facing southward.



Photo 3. View of exposed soils at the northwester access entrance. This area needs better stabilization and sediment controls.



Photo 4. View of damaged silt fence and exposed soils that are not protected (also downslope from silt fence in lower left portion of photo), in the northwestern portion of the project area.



Photo 5. View of the eastern portion of the project area from the southeastern corner facing northward. Silt fence along the perimeter is in disrepair.



Photo 5. View of the southern portion of the project area from the southeastern corner facing northward. Silt fence is in disrepair.



Photo 5. View of musk thistle (*Carduus nutans*) and houndstongue (*Cynoglossum officinale*) within the project area