

## Inspection Photos

Location Name: Dryer - 67N60W /14NWNW

Location #: 306577



**Photo #1**

**Dryer 1 (API # 05-123-24398) wellhead**

**Wellhead sign w/ emergency contact info has been posted**



**Photo #2**

**Dryer 1 & April 12-14 Battery**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

**Location Name:** Dryer - 67N60W /14NWNW

**Location #:** 306577



**Photo #3**

**Dryer 1 (API # 05-123-24398) wellhead**

*Previous photo from SEP-2016 FIR showing soil stain*



**Photo #4**

**Dryer 1 (API # 05-123-24398) Pumping Unit**

*Previous photo from SEP-2016 FIR showing soil stain*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Location Name: Dryer - 67N60W /14NWNW

Location #: 306577



**Photo #5**

Dryer 1 (API # 05-123-24398) wellhead

*Stained soil near wellhead & pumping unit appears to have been addressed*



**Photo #6**

Dryer 1 (API # 05-123-24398) wellhead

*Bradenhead does not appear plumbed to surface*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

Location Name: Dryer - 67N60W /14NWNW

Location #: 306577



Colorado Oil & Gas Conservation Commission  
40.58074, -104.067, 1480.0m, 214°  
2018/08/17 12:16:00 PM

**Photo #7**

**Dryer 1 (API # 05-123-24398) Engine**

***Stained soil near engine base***



Colorado Oil & Gas Conservation Commission  
40.58071, -104.06701, 1482.0m, 303°  
2018/08/17 12:15:23 PM

**Photo #8**

**Dryer 1 (API # 05-123-24398)**

***Gearbox stain & apparent seepage***



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Location Name: Dryer - 67N60W /14NWNW

Location #: 306577



### Photo #9

Dryer 1 (API # 05-123-24398)

**Unused equipment (belt guard)**

**55-gal. Drum, labeling / placard appears illegible**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources