

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/17/2018

Submitted Date:

08/18/2018

Document Number:

691200347**FIELD INSPECTION FORM**Loc ID 306577 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 76840Name of Operator: SCHNEIDER ENERGY SERVICES INCAddress: P O BOX 889City: FORT MORGAN State: CO Zip: 80701**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**14 Number of Comments5 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Schneider, Jeff	970-867-9437	jeff@schneiderenergy.com	President
Bothwell, Kevin	970-867-9437	kevin@schneiderenergy.com	Vice-President
Pesicka, Conor		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
289838	WELL	PR	03/01/2018	OW	123-24938	DRYER 1	SI

General Comment:

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action	L		Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign has been posted at wellhead which addresses the CA from previous FIR #684902409.		
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	CONTAINERS		
Comment:	55-gal. Drum, labeling / placard appears illegible.		
Corrective Action:	Comply with Rule 210.e using the Rule 210.e guidance document for further details.		Date: 10/19/2018
Emergency Contact Number:			
Comment:	Emergency contact info has been posted at wellhead which addresses the CA from previous FIR #684902409.		
Corrective Action:			Date:
Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Unused pump jack belt guard.		
Corrective Action:	Comply with Rule 603.f using the Rule 603.f guidance document for further details.		Date: 09/19/2018
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	PUMP JACK		
Comment:	Heavy iron mesh		
Corrective Action:			Date:
Equipment:			
Type: Deadman # & Marked	# 4	corrective date	
Comment:			
Corrective Action:			Date:
Type:	#		

Comment:	Refer to FIR #691200345 for additional equipment details.		Date:	
Corrective Action:			Date:	
Type: Pump Jack	# 1			
Comment:	Stained soil at wellhead & near pump jack appears to have been remediated. Thich addresses the CA from previous FIR #684902409. Gearbox appears to have stain and seepage.		Date:	
Corrective Action:	Remediate stained equipment; Securely fasten all valves, pipes, and fittings to ensure good mechanical condition per Rule 605.d.		Date:	09/19/2018
Type: Prime Mover	# 1			
Comment:	Gas engine (Ajax). Stained soil appears near engine base.		Date:	
Corrective Action:	Remove or remediate stained soil; Securely fasten all valves, pipes, and fittings to ensure good mechanical condition per Rule 605.d.		Date:	09/19/2018

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.577190,-104.066593
Comment:	This centralized battery services 2 location ID's. (317498, 306577). Refer to FIR #691200345 for Tanks & Berms details.				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:	Observed wellhead stuffing box venting with loud audible hissing. Operator President Jeff Schneider met COGCC field inspector Bret Evins on adjacent April 12-14 location at approximately 2:30pm today. Mr. Schneider informed me that he would make mechanical adjustments to stop the venting immediately.	
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected FacilitiesFacility ID: 289838 Type: WELL API Number: 123-24938 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: Observed well was shut-in with valves closed at wellhead. Pump jack and engine were also shut-down.
Operator President Jeff Schneider met COGCC field inspector Bret Evins on adjacent April 12-14 location at approximately 2:30pm today. He disclosed that well would be SI until separator can be replaced.

Corrective Action: _____

Date: _____

BradenHead

Comment: Bradenhead does NOT appear plumbed to surface.

Corrective Action: Plumb bradenhead to surface; Securely fasten all valves, pipes, and fittings to ensure good mechanical condition per Rule 605.d.

Date: 09/19/2018

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? Pass

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? Pass

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? Pass

Comment _____

Corrective Action _____

Date _____

- 1003b. Area no longer in use? _____ Production areas stabilized ? _____
- 1003c. Compacted areas have been cross ripped? _____
- 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
- Cuttings management: _____
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
- Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads _____ Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
691200348	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4555399