

# Inspection Photos

Operator: Gunnison Energy

API: 05-051-06120

Date: 7/25/2018



**Photo 1. View of the project area from the southeastern edge facing center.**





**Photo 2. View of the southeastern portion of the project area from the southeastern edge facing southwestward.**





**Photo 3. View of the northeastern portion of the eastern edge facing northwestward.**





**Photo 4/5. View of the what appears to be herbicide treated musk thistle (right) and untreated bull thistle and debris (left) within the southeastern portion of the project area.**